


FIG. 1



F I G. 2A




FIG. 2B




FIG. 3








FIG. 4

	CURSOR ON SCREEN	STATE OF PEN (SCREEN STATE)	PEN SIDE SWITCH : STATE
1		POINT B STOP (CURSOR STOP)	SWITCH42a : OFF SWITCH42b : OFF
2		POINT A POINT B	OSCILLATION (CURSOR MOVEMENT)
3		POINT A POINT B 104	OSCILLATION (DRAW)
4		POINT A POINT B 104	STOP (CURSOR STOP)

F I G. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13

PEN				MAIN BODY		
OPERATION MODE	SW41	SW42a	SW42b	DRIVING INTERVAL (T)	OUTPUT COORDINATE MODE	Z-AXIS DIRECTION COORDINATE VALUES
PEN INPUT (Mode=1)	ON	OFF	OFF	T1	ABSOLUTE COORDINATES	50 mm OR LESS
PROXIMITY INPUT (Mode=2)	ON→OFF	OFF	OFF	T11	ABSOLUTE COORDINATES	300 mm OR LESS
REMOTE INPUT1 (Mode=3)	OFF	ON	OFF	T2	RELATIVE COORDINATES	400 mm OR MORE
REMOTE INPUT2 (Mode=3)	OFF	ON	ON	T21	RELATIVE COORDINATES	400 mm OR MORE
REMOTE INPUT1,2 (Mode=3,4)	OFF	ON	ON or OFF	T2 or T21	RELATIVE COORDINATES	k_0
REMOTE INPUT1,2 (Mode=3,4)	OFF	ON	ON or OFF	T2 or T21	RELATIVE COORDINATES	$0.4 \sim 2m$
REMOTE INPUT1,2 (Mode=3,4)	OFF	ON	ON or OFF	T2 or T21	RELATIVE COORDINATES	$2 \sim 4m$
REMOTE INPUT1,2 (Mode=3,4)	OFF	ON	ON or OFF	T2 or T21	RELATIVE COORDINATES	$4 m$ OR MORE

FIG. 14




FIG. 15




FIG. 16

PEN OPERATION MODE		PEN POINT SW41	PEN SIDE SW1 42a	PEN SIDE SW2 42b	Z-AXIS DIRECTION CALCULATED COORDINATE VALUES	OUTPUT COORDINATE VALUES	
PEN UP	PEN DOWN					ABSOLUTE COORDINATES	RELATIVE COORDINATES
PEN INPUT	○	OFF	OFF	OFF	—	—	—
	○	ON	—	—	(0)	○	○
PROXIMITY INPUT	○	OFF	ON	OFF	PREDETERMINED VALUE 1 OR LESS	○	○
	○	OFF	OFF	ON	PREDETERMINED VALUE 1 OR LESS	○	○
REMOTE INPUT	○	OFF	ON	ON	PREDETERMINED VALUE 1 OR LESS	○	○
	○	OFF	ON	OFF	PREDETERMINED VALUE 2 OR MORE	○	○

FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22





FIG. 23



F I G. 24

25/25

PEN OPERATION MODE		PEN POINT SW41 42a	SW1 42b	SW2 42b	Z-AXIS DIRECTION CALCULATED COORDINATE VALUES	COORDINATE EFFECTIVE	OUTPUT COORDINATE VALUES	
PEN UP	PEN DOWN						ABSOLUTE COORDINATES	RELATIVE COORDINATES
PEN INPUT	○	OFF	OFF	OFF	-	-	-	-
	○	ON	-	-	Z=0	○	○	○
PROXIMITY INPUT	-	-	ON	-	-	0<Z<PREDETERMINED VALUE1	x	-
	○	OFF	ON	OFF	0<Z<PREDETERMINED VALUE1	○	○	○
PROXIMITY INPUT	○	OFF	OFF	ON	0<Z<PREDETERMINED VALUE1	○	○	○
	○	OFF	ON	ON	0<Z<PREDETERMINED VALUE1	○	○	○
REMOTE INPUT	-	-	ON	-	-	PREDETERMINED VALUE2<Z	x	-
	○	OFF	ON	OFF	PREDETERMINED VALUE2<Z	○	○	○
REMOTE INPUT	○	OFF	OFF	ON	PREDETERMINED VALUE2<Z	○	○	○
	○	OFF	ON	ON	PREDETERMINED VALUE2<Z	○	○	○